
precision colors

Full-strength Cyan (C). Use it when the nozzle check shows gaps in Cyan only.

PURGE PAGE

Cyan Solid



100%