
precision colors

PURGE PAGE

Cyan Solid

Full-strength Cyan (C). Use it when the nozzle check shows gaps in Cyan only.

100%



Plain paper setting | Color management off | 1 to 3 sheets, then a nozzle check